

PRODUCT DATA SHEET

NORGLASS LABORATORIES PTY.LTD.

A.B.N. 92 001 807 245

P.O. Box 312, Neutral Bay. NSW 2089 Australia

59 Moxon Road, Punchbowl NSW

Ph: 61 2 9708 2200 Email: techinfo@norglass.com.au

Web: norglass.com.au



WEATHERFAST PREMIUM ENAMEL

DESCRIPTION:	A single pack, low odour, high gloss enamel with excellent weathering characteristics and gloss retention in salt laden environments.
USES:	Can be used on most surfaces including timber, steel, aluminium, concrete. For all areas of severe exposure, and interior applications. Not recommended for areas of continuous immersion. Note: Area should be primed first with the appropriate primer.
SIZES:	4 litre, 1 litre, 500ml, 250ml and 100ml. (White also available in 10L & 2L)
PROPERTIES (at 20°C)	
COLOUR:	19 standard colours, plus black & white. Black & White also available in a Satin Finish.
TOXICITY:	See Precautions and refer to Safety Data Sheet
FINISH:	High gloss
COVERAGE:	10 - 12 m ² per litre
DRYING TIME:	Touch dry after 2 hours and 50% relative humidity.
RECOATING:	After 16 hours.
POT LIFE:	N/A
MIXING RATIO:	N/A
THINNING:	See Application section.
WEIGHT/LITRE:	0.930 – 1.200 kg (depending on colour)
VOLUME SOLIDS:	51% (White), varies with colours
FLASH POINT:	32°C.

CLEAN UP:	WEATHERFAST BRUSHING or SPRAYING THINNERS
U.N. NUMBER:	1263
TRANSPORTATION:	DG Class: 3 HAZCHEM: 3Y P.G III
PREPARATION:	New Timber: Prime with NORSEAL (if required). Use Norglass PRi-COAT, minimum 2 coats, allowing 24 hours (minimum) drying between coats. Finish with 2 coats of Weatherfast Premium Enamel. Previously painted surfaces: Clean down with NORCLEAN-PLUS and remove flaking or unsound paint. Sand with 280-360 grit sandpaper to remove any existing gloss. Note: On new Galvanised Iron or Aluminium, pretreat with Norglass METAL -ETCH. OTHER SUBSTRATES: Refer to appropriate surface and product Information sheets.
APPLICATION:	Stir contents before use. Brush or Roller: Use a Nylon brush or a short nap roller. In hot weather a maximum of 5% WEATHERFAST BRUSHING THINNERS may be added to assist flow. Spraying: For conventional spray equipment, use 25-33⅓% of WEATHERFAST SPRAYING THINNERS or according to the spraying equipment used. May be sprayed wet on wet. The use of yellows and oranges are notoriously difficult to obtain coverage when applied over a less than uniform background. Any patchy areas will still show through after several coats of Northane or Weatherfast enamel. This is a problem with all yellow and orange lead free pigments regardless of manufacturer. The only solution is to make sure the background colour is completely uniform before painting i.e. uniformly white, grey, blue Etc.
PRECAUTIONS:	Wear protective clothing and use personal protective equipment as required Keep away from heat, sparks, open flames or hot surfaces. No smoking. Use only non-sparking tools. Take precautionary measures against static discharge. Avoid breathing fumes or vapours. Wash hands thoroughly after handling. Avoid release to the environment. Store locked up, in a well-ventilated place. Keep cool. Keep out of reach of children
SPECIAL INSTRUCTIONS:	Do not use this product below 10°C as drying and gloss will be affected. Screen external surfaces away from dew for a minimum of 6 hours after painting.
FIRST AID:	If poisoning occurs call a doctor or Poisons Information Centre (Aust) on 131126 or (NZ) 0800 764 766 and have label information ready. If in Eyes rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. If eye irritation persists get medical advice. If on Skin wash with plenty of soap and water. Take off contaminated clothing and wash before re-use. If skin irritation occurs get medical advice/attention. If Swallowed rinse mouth. DO NOT induce vomiting. Give a glass of water. Never give anything to the mouth of an unconscious person. If vomiting occurs, place victim face downwards, with the head turned to the side and lower than the hips to prevent vomit entering the lungs. If Inhaled remove person to fresh air. Remove contaminated clothing and loosen remaining clothing. Allow person to assume most comfortable position and keep warm. Keep at rest until fully recovered. Get medical advice if breathing becomes difficult.